

RECEIVING AND ESTIMATING REPORT

1R 92-^{ORDER}11529

INITIAL JJM	CUSTOMER ORDER NO. 158552		DATE RECEIVED 05/06/92		DATE OPENED 05/18/92		DATE CODE WW 8-72		SERIAL NUMBER 6590847		NEW SERIAL NUMBER 700		MODEL AND GRADE 7MMAG		ADL ADL	
ACCESSORIES W/STUDS																

FROM:	BURNETT, TRAVIS BURNETT PAINT & WALLPAPER CO 702-C E ROBINSON SPRINGDALE AR 72764	SHIP TO:	BURNETT, TRAVIS BURNETT PAINT & WALLPAPER CO 702-C E ROBINSON SPRINGDALE AR 72764
-------	--	----------	--

CUST NO: 061946 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER NO	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					5-20	UPS

GUN CONDITION		REPAIR CHARGE	
☐ NEW		EXCISE	
☐ LIGHTLY WORN		TAX	
☐ WORN		INSURANCE	
☐ VERY WORN		UPS	
☐ UNREPAIRABLE		PARCEL POST	
☐ MARRED		TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLER	Fire	B1	on safety	release		
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

As required, complaint could be duplicated. Unusually I left
trigger assembly, but trigger completely unaffected further
evidence missing from all adjusting screws - 1) excessive over-travel 2) excessive
engagement 3) trigger pull only 2 1/4 pounds - trigger had no return
action and many times during test, firing pin simply followed down when
closing bolt.
Trigger pull 2 1/4 pounds; over-travel .0065"

[illegible]

OFFICE COPY

RD6925 REV. 1/92