

Remington.



bcc: Arms Service-R-89-1086
Fit new trig. assm, clean
action & check feeding

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

April 26, 1989

Caddo Arms & Cycle Works
1400 Fairfield
Shreveport, LA 71101-0000

Dear Sir:

Examination has been completed on the Model 700 BDL 270 caliber rifle, serial number B6274396, which you returned covered by your order 2031, because the rifle allegedly fires when the safety is released, and it is not feeding properly.

The returned firearm, which was produced in December of 1980, has been thoroughly examined by our experts and found to have our high-pressure proof test, gallery test, and final inspections stampings, indicating that it had successfully passed all necessary tests and inspections before being shipped from our factory.

The general condition of the rifle appeared to be very good, and it was noted that scope mounts had been added. In going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not produce the alleged complaint of the rifle firing when the safety was released. All tolerances and dimensions were found to be normal, trigger pull was measured to be 4-1/2 pounds, and the sear lift with the safety in the on safe position was within specifications at .008.

Removal of the barrel action from the stock assembly revealed that the underside of the receiver and trigger assembly were wet with excessive lubrication. The inside of the trigger assembly was also contaminated with excessive oil (?). In future use, we recommend