

March 18, 1975

Les Freer Gun Shop  
8928 Spring Branch Drive  
Houston, Texas 77055

Dear Les:

Thank you for forwarding the Model 600, Serial Number 6651698, and the Model 700, Serial Number 6336761, to us for inspection of the fire control problems.

We could duplicate both conditions which you described, following your sequence of operations. On both guns we found that the firing pin head was binding, holding it back until some action would free it, and it would come forward. On the Model 600 we also found that the sear safety cam was binding in the housing. On fire control problems of this type, when a new fire control assembly is installed, the freedom of movement of the firing pin head also should be checked.

We appreciate your sending these guns back, and would like you to return any guns of this or the previously discussed type for our inspection. Would you please contact George Martin as you did this time.

Thank you again for your consideration.

Sincerely yours,

John P. Linde, Manager  
Manual Firearms Design  
Illion Research Division

JPL:T

AL 0031984