

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 2/26/90	DATE OPENED 01/03/91	DATE CODE	SERIAL NUMBER A6445396	MODEL AND GRADE 700 270 BDL	ORDER R 91-0018c		
ACCESSORIES				L/STUDS CO 4-77 2ND TIME IN			
FROM: CONTI, CARMINE P 89 RICCIARDONE AVE TORRINGTON CT 06790				SHIP TO: CONTI, CARMINE P 89 RICCIARDONE AVE TORRINGTON CT 06790			
COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA V412095796	
<p>PAIR CHARGE TAX INSURANCE UPS PARCEL POST TOTAL</p> <p>UN CONDITION: <input type="checkbox"/> NEW <input type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED</p> <p>STOMER'S REQUEST</p> <p><i>"Fires when safety moved forward"</i></p> <p>IN FAULT <i>Toggin assembly is rusted - toggin and connector not moving freely on pivot pins. Disassembly of barrel action from slide revealed inside side of barrel and receiver have rusted areas. It appears that the rifle became wet in use and was not disassembled for proper cleaning and maintenance.</i></p> <p><i>Replace toggin assembly at no charge, as a gesture of good-will.</i></p> <p><i>When rifle is returned, please include a copy of the new M/700 owner's manual which outlines proper lubrication and maintenance procedures.</i></p>							
REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		

OFFICE COPY

RD6925 REV. 7/90