

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

bcc: Arms Service
R89-01964
hold for reply
B. Ericson
J. Hutton

February 6, 1989

Dave's Gun Shop
R.D. #3, Box 726
Drums, PA 18222

Dear Sir:

Examination has been completed on the Model Seven 308 Win. caliber rifle, serial number 7635171, that you returned to us a short time ago because the gun fired on two occasions when closing the bolt.

The returned firearm, which was produced in September 1984, was found to bear our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the rifle appeared to be very good. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the condition that was reported. Factory seals were intact on the trigger adjustment screws indicating that no adjustment had been made to the trigger outside our factory. Trigger pull was measured to be 4-1/2 pounds, and sear lift with the safety in the on position was well within specifications at .0125". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Since we found the firearm to function normally in every respect, we are prepared to return it to you in its present condition.