

*Remington.*



bcc: Arms Service  
R-89-04149  
HOLD FOR REPLY  
COPY TO BILL ERICSON - ALL

## REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 13, 1989

Mr. Robert Davis Tile  
Attn: Mr. Robert Davis  
Box 265, R.D. 2  
No. Guernsey Ave.  
West Grove, PA 19390

Dear Mr. Davis:

Examination has been completed on the Model 700, 17 Rem. rifle, serial number A6573007, that you recently returned to us.

The rifle, which was produced in February of 1978 has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests prior to being shipped from our plant.

The general condition of the firearm appeared to be very good, and in going over the individual parts, we found headspace, recoil shoulders, and chamber all to be normal.

Examination of the action and trigger assembly could not duplicate the malfunction you reported. Many attempts were made to duplicate the problem. All adjustments seem to be to factory specifications and no alterations have been made outside the factory. The trigger pull was measured at 3 lbs. and the sear lift with the safety in the on-safe position was well within specifications at .011". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Since we found the mechanism to function normally in every re-