-2-

be used sparingly and not let accumulate in or on the trigger as this condition can adversely effect its operation. .

As requested, as a gesture of good-will and to insure that our customer's faith in the rifle is restored, we will install a new trigger assembly at no-charge. Please allow sufficient time for this service and return of the rifle.

Thank you for affording us the opportunity to be of service, and we trust that our handling meets with approval.

Sincerely,

A. Stekl, Specialist.

Product Service

JAS: tpp

Remington Arms Company, Inc.