

R 93-11373

INITIAL JJM	CUSTOMER ORDER NO.		ATTN J. Kest			
DATE RECEIVED 05/05/93	DATE OPENED 05/06/93	DATE CODE AC 3-82	SERIAL NUMBER B6375990	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL
ACCESSORIES W/STUDS			L/REAR SIGHT			
FROM: <i>Steph</i> DORNS GUN SERVICE 4388 MERCER UNIVERSITY MACON GA 31206			SHIP TO: <i>XC F. Smy</i> DORNS GUN SERVICE 4388 MERCER UNIVERSITY MACON GA 31206			

CUST NO: 001078 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION			REPAIR CHARGE		
<input checked="" type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED			EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Left mag 1982 - Unable to duplicate Customer concern. Examination revealed sticky substance on action, and trigger adjustment on trigger assembly and bolt stop release. This substance appears to be oil. The trigger adjustment now has been triggered with no problems.*

COMMENTS *Found to product source for evaluation D. Santa*

Repair Complete trigger assembly at 1/2 normal adjustment cost & the action is good & good will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5925 REV. 1/91