

BARBER - Kinzer PPS GAL RE0001519

Remington Arms Company Inc.
Arms Service Division
Ilion, NY 13357

JULY 26, 1988

TO: KEN GREEN
FROM: KEVIN A. CORNELL
SUBJECT: DOUG DUMBLETON XP-100 B7520484

Jim Stekl's letter quite clearly diagnosis the problem. The gun shows signs of **extremely** high pressure loads. The customer was using handloads by his own admission. Several Remington experts including Jim Stekl, Jack Kast, Herb Brown, and Fran Cole have reviewed the facts. This is not a warranty repair.

Fran has made quite a generous offer to the customer at \$295.00 (MSP), this is considerably less expensive than the gun would cost the customer to replace on the open market.

The "Form Letter" does reference exactly what happened to the gun, **HIGH PRESSURE LOADS.**

In conclusion, this is not a warranty repair.

cc:Jim Stekl
Bruce Beardwood