

PROJECT#241095

[illegible]

Coverpg

BARBER - 5.22.06r0001572

85

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710Project: 241095Rifle: C-8TLW #: TLW0300Date: 12 / 15 / 00Inspector: JesseRound Level: 500☒ Measure Headspace: Min 4.003☐ Sear Engagement: .0312 .0301 .0304☒ Trigger Pull: 1st 3.75 2nd 4.0 3rd 4.0 Ave. 3.92

Check the following areas for signs of unusual wear or breakage:

☒ Receiver insert☒ Rear surface of Bolt Lugs☒ Check for "galling" on rear of Bolt Lugs☒ Bolt Plug☒ Bolt Plug Insert "ears" on firing pin assembly☒ Check for loose or missing pins - make note and re-stake if necessary☒ Check plastic inserts for cracks or other damage.☒ Firing Pin Head for Looseness.☒ Check Firing Pin Tip for Looseness.☒ Check Take Down Screws for Movement. Show new position relative to original mark. Rear Middle Front

Position after re-torque:

 Rear Middle Front☒ Check Diaz Bracket Screw for looseness.☒ Check Bolt Stop 51.24T material movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below.

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07404