

Setup file

REPAIR GUN INQUIRY FUNCTION: E (N)EXT (P)REV (I)NQ (E)XACT 07/25/90
 ENTER REPAIR NUMBER -----> 9018689 16 07 30
 B6719276
 FROM: (CUST NUM: 025562) EGGERT MODEL: 700
 EGGERT, TROY GA/CAL: 0030-06
 19319 OXFORD STREET TYPE: BDL
 ACCESSORIES: W/STUDS
 HARD CASE

ELK RIVER MN 55530
 SHIPPED TO:

612-493-2749

DATE CODES: PF 6-85
 OTHER ACCESSORIES:

COMMENTS: HARD CASE RETURNED 7-25-90

DATES:		TO		FROM		
RECEIVED	06 25 90	GALLERY	07 16 90	07 17 90	ENTERED BY:	JJM
OPENED	07 02 90	PROD SERV	00 00 00	00 00 00	REPAIRMAN:	RF
ESTIMATED	07 13 90	TAG GUNS	00 00		TYPIST:	
PROMISED	00 00 00	REJECTED	00 00		CORRESPONDENT:	
REPAIRED	00 00 00	CASH RECEIVED:\$	0.00			
SHIPPED	07 23 90					
BILL TYPE	N/C	PF1 =	VIEW DETAIL			

REPAIR NUMBER: 9018689 NO CHARGE EST/LETTER LSTD 07/25/90
 CUSTOMER NAME: EGGERT, TROY 16 07 41

REQUEST: MISFIRED, SCRATCHED AND MARRED BOLT. STOCK SCRATCHED.
 MAIN FAULT: FRONT GUARD SCREW TOO LONG CAUSING BOLT NOT TO FULLY CLOSE.
 BOLT SHOWS ABNORMAL WEAR FOR CONDITION OF RIFLE, WE WILL
 REPLACE IT. WE CANNOT BE RESPONSIBLE FOR A STOCK SCRATCHED
 OUTSIDE OF OUR CONTROL.

PARTS:	\$	0.00	1	92897 BOLT ASSEM (BDL 270 - 30-06 MAX)
LABOR:	\$	0.00	CHAMBER EXTREMELY RUSTY, MUST BE KEPT CLEAN AND LIGHTLY	
	\$	0.00	OILED	
	\$	0.00	POLISH CHAMBER	
	\$	0.00	ADJUST FRONT GUARD SCREW	
	\$	0.00	SEND OWNERS MANUAL	
	\$	0.00	PROOF, CLEAN, TEST	

CLEAR = RETURN
 NO MORE DATA AVAILABLE FOR THIS REPAIR