

CAL.- 30.06

#3

PROJECT#241095

[illegible]

Coverpg.

BARBER - 5-22-06+0001582

6

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710Project: 241095Rifle: C-13TLW #: TLW0300Date: 12 / 15 / 00Inspector: JesseRound Level: 500☒ Measure Headspace Min +.002☒ Sear Engagement: .0251☒ Trigger Pull: 1st 4.25 2nd 4.5 3rd 4.5Ave. 4.42

Check the following areas for signs of unusual wear or breakage:

☒ Receiver insert☒ Rear surface of Bolt Lugs☒ Check for "galling" on rear of Bolt Lugs☒ Bolt Plug☒ Bolt Plug Insert "ears" on firing pin assembly☒ Check for loose or missing pins - make note and re-stake if necessary☒ Check plastic inserts for cracks or other damage.☒ Firing Pin Head for Looseness.☒ Check Firing Pin Tip for Looseness.☒ Check Take Down Screws for Movement. Show new position relative to original mark.

☒ Rear	☒ Middle	☒ Front
--	--	---

Position after re-torque:

☒ Rear	☒ Middle	☒ Front
--	--	---

☒ Check Diaz Bracket Screw for looseness.☒ Check Bolt Stop Material Movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below.

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07414