

Remington Arms Company Inc.
Arms Service Division
Ilion, New York 13357

February 6, 1989

Dear Remington Arms;

As per our phone conversation, I am including a description of the problem with my Model 700.

I was in the process of putting a new stock on the rifle. I decided to move the safety from "S" to "F" and found that it would not move. I used a plastic handle from my screw drive and tapped the safety lever. The lever appeared to move after I tapped the safety lever several times. I then pushed the safety lever to the "F" position and the firing pin moved forward as if the trigger was pulled. I worked the safety lever several times and it appeared to work fine. I then operated the bolt through a full cycle. I then tried the safety lever several more times, nothing happened. I decided to put the rifle away, but tried the safety one more time. This time the safety lever was hard to move. I push harder, pushing the safety lever to the "F" position and this time the firing pin actuated as if the trigger was pulled.

This is what happened as I remember it. I hope I have explained clearly what has taken place so appropriate repairs can be completed.

Thank You

Daniel R. Fagan
1305 20 th St.
Oceanside, CA 92045

MODEL 700 Serial No. C6218514

P.S. If addition questions arise and you need to contact me, my phone number is 805-481-7569