

In 1985 I bought a Model 7--243 bolt action. This gun has, thus far, worked properly. What I would like to know is 1) What can Remington do about my 270? and 2) Does the Model 7 safety (Which can be left on during unloading) have this same problem?

Thank you for your attention to this problem. I am waiting to hear if there is a solution.

Sincerely,

*Douglas Hamann*

Douglas Hamann