



REMINGTON ARMS COMPANY, INC.

1-40 & Remington Road
Lonoke, AR 72086
501/676-4197

CUST. ORDER:

Mrs. Clinton Harlow

Rt. 8, Box 5

Llano, TX 78643

Date: 2/28/92

File # 34129

PROPERTY DAMAGE

The damaged Mdl 700 .222 Rem. Mag. rifle and 19 (2 fired, 17 unf.) R222M1's
you returned ~~has~~ (have) been received and submitted to our ballistics laboratory for examination. A report of our test results will
be sent to you in approximately 6 weeks.

Any inquiry should
show above file number

PLEASE RETURN EXHIBITS TO P.S.O.

W. T. SMITH
Product Service Supervisor

RECEIVED 2/28/92

PD 1186 X
2186

To: Ballistics

Code: H15P 12/77

Firearm Mfg:

Rem. Mdl. 700 ^{.222 Rem} mag
S/N 201936

Complaint: Case separation/gun damage

Test for: 1. Shoot for V&P

2. Cause of case separation

3. Comment

4.

5.

Report: No defect found. The case appeared to separate in the most unstable
spot after several reloadings - See attached sheet.

SHELLS HAVE NOT BEEN RELOADED

V&P: A LITTLE LOW

RECEIVED

Unconfirmed
MAR 06 1992

Approved:

Date:

PRODUCT SERVICE

Approved:

Date:

Returned to Product Service Office:

Ridley J Buckmaster

Date:

3-5-92