

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

October 20, 1988

Mr. Jon A. Haynes
R.R. #3
Box 211
Clinton, IN. 47842

Dear Mr. Haynes:

Examination has been completed on the Model 700 .22-250 Rem caliber barreled-action only, serial number 6607224, which you returned to us because "it discharged when I moved the safety to the fire position".

The returned firearm, which was produced in January of 1973, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

Examination of the trigger assembly revealed that the weight-of-pull and overtravel screws had been adjusted outside our factory. As received, the trigger pull measured 2 1/2 pounds and did not have positive retraction. Our minimum factory pull specification is 3 pounds. We strongly recommend against any adjustments to the trigger assembly outside our factory, because malfunctions like you experienced can result.

We are, as a gesture of good-will, going to install a new trigger assembly in your rifle, properly adjusted to our minimum specification of 3 pounds, at no-charge, to restore your faith in the rifle. However, do not attempt to further adjust the assembly yourself. Please allow 2-3 weeks for processing and return of your rifle.

Thank you for allowing us the opportunity to examine the rifle, report our findings, and to be of service to you.

Sincerely,

J.A. Stekl
Specialist
Product Service

JAS/nb