

CUSTOMER ORDER NO.		COMMENTS ST JOHN	
RECEIVED 14/88	DATE OPENED 11/21/88	DATE CODE BB 1-81	SERIAL NUMBER A6833231
MODEL AND GRADE 700 30-06 BDL		ORDER R 88-31071	
SOURCES SLING STRAP W/STUDS		W/SWIVELS	

TO:	SHIP TO:
JAMES HUFFORD 13 LAKEWOOD LN. PINE BLUFF, AR. 71603	JAMES HUFFORD 13 LAKEWOOD LN. PINE BLUFF, AR. 71603

INT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	FROM DATE	ESTIMATED	VIA V019642446
------------	--------------------	--------------------------------	-----------	-----------	-------------------

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

MEYER REQUEST

"Rifle has been known to malfunction at very unexpected times".

FAULT

Close of action and trigger loaded with excessive lubrication. Bolt stop and rear safety cam move very sluggishly - much of trigger assembly also contains excess lubrication accumulation.

- 1) Clean excess oil off action*
- 2) Install new bolt-lock safety trigger assembly at no charge.*
- 3) expedite return of rifle to owner.*

11/28/81
JLS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD0923 REV. 6/88