

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/26/90	DATE OPENED 01/03/91	DATE CODE ED 10-83	SERIAL NUMBER R6492095	MODEL AND GRADE 700 270 BDL/LH		ORDER R 91-002	
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:

J R 'S GUNSMITHING
KEARNEY COMMERCIAL CNTR
KEARNEY MO 64060

SHIP TO:

J R 'S GUNSMITHING
KEARNEY COMMERCIAL CNTR
KEARNEY MO 64060

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Triggers malfunctions, rifle is not safe"

MAIN FAULT

Trigger assembly has been removed outside of factory and improperly re-installed. Safety arm was lodged under gun safety cam as previous; could not be moved. Sides of trigger housing were caved in due to improper replacement of retaining pins, binding the rear-safety cam from movement.

PARTS

Send quotation for new trigger assembly - prevent assembly & beyond again.

REPAIRMAN GALLERY TESTER	PROOF DATE	CLEAN DATE	TEST DATE	TARGET DATE	PATTERN DATE
-----------------------------	---------------	---------------	--------------	----------------	-----------------

OFFICE COPY

RD0925 REV. 7/90