

March 18, 1991

Remington Arms Co., Inc.
Ilion, New York 13357

Dear Remington;


The returned Remington, Model 700, Serial # 6248783, is firing when the safety is released. This is sometimes after the trigger has been pulled while the safety is on, then taken off. At other times the sear will not hold the firing pin when the bolt has been cycled.

I am also interested in having the gun reblued. Please quote me a price on rebluing.

Please repair and return to:

J T's Gun & Pawn Shop
209 Main Street
Hazard, KY 41701
(606) 439-4347

Thank you,



JOE N. TURNER, Owner