

June 19, 1981

Dear Sir,

Please replace this faulty
trigger on the Remington.
Several times it has now fired.

Thank You
Gary T. Halishek
Route 2 Box 422
Stadstone, Mich.
49837

MODEL: 600

S/N: 77404

DATE: 6-29-81

FROM: GARY HALISHEK

Rt 2 Box 422

GLADSTONE MI

GUS: A6654959

CODE: DO = 9-78

QA/CAL: 308

CHECKED BY: M. HART

APPROVED: 4/21/81

APPROVED: 9/1/81

APPROVED: 9/1/81

APPROVED: 9/1/81

APPROVED: 9/1/81

SS FIRED SEVERAL

mer complaints.

assemble new fire control - clear area in
stock for fire control.