

James L. Keith
1018 Taurus Drive
Edmond, Oklahoma 73034
(405) 348-9766 (HOME)
(405) 341-2284 (WORK)

Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, New York 13357

February 4, 1991

Gentlemen,

Pursuant to my conversation with your repair department, I have returned my Remington Model 700 for inspection and repairs.

Recently while on a hunting trip my rifle discharged while attempting to unload it. After hunting for several hours without firing or moving the safety lever to the fire position, I attempted to unload the rifle. When I moved the safety lever to the fire position to open the bolt the rifle discharged into the ground. I did not touch the trigger nor drop or jar the rifle in any way.

I have several newer Remington bolt action rifles in which the bolt can be opened with the safety lever in the safe position. If it is possible to modify this rifle with a new style trigger and safety mechanism, please do so!!!

I would appreciate acknowledgment of your receipt of this rifle. After inspection and repair, please return the rifle to the address listed above

Sincerely,


Jim Keith

REMINGTON MODEL 700 - 30/06 (Serial Number: A-6344541)