

*Remington.***REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 31, 1989

Mr. Richard Loehlein  
2201 Irene St.  
Roseville, MN 55113

Dear Mr. Loehlein:

Examination has been completed on the Model 700 BDL 30-06 caliber rifle, serial number A6334180, that you returned to us because of the accidental discharge you experienced.

The returned firearm, which was produced in July of 1976, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the gun appeared to be very good and, in going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not produce any malfunctions. All tolerances and dimensions were found to be normal. Trigger pull was measured to be 5-1/2 pounds, and the sear lift with the safety in the "on-safe" position was well within our specifications at .007". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Since we found the firearm to function normally in every respect, we are prepared to return it in its present condition. However, a trigger assembly with a safety that allows the bolt to be opened with the safety on, can be installed for \$15.00 net.

Should you desire the new trigger assembly, please include a check in the above amount made out to Remington Arms Co., Inc., with your