

Softly won't work 3 Trigger
 Case off without Pulling
 when working Bolt

REM. 700 30-06
 6355141

RECEIVED SUPPLY
 100 200
 100 200
 100 200
 100 200
 100 200

EL: 700 200
 16802
 6-12-88
 2901, 4024 11-
 MIDLAND CITY 6-
 6355141
 OT: 7-70
 CAL: 3006
 CHECKED BY: 110 H.A.R.
 APPROVED: GON 6/24/88
 APPROVED: REX 6/24/88
 APPROVED: P.T. 6/24/88
 APPROVED: X.O. 6/24/88
 LIST ON 306
 RECORD 100

SA 6005 000
 KIVE 827

COMMENTS:

Fire control - rummed up rear safety can stick
 in down position. excessive quirk in fire control.
 Replace fire control - change customer.

- Trigger pull 3#
- gun passes tick test.