

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

May 13, 1988

Mr. William G. MacFarland
R.D. 2
Prizer Road
Pottstown, PA 19464


Dear Mr. MacFarland:

Examination of your rifle Model 700, 30-06 caliber, serial number 6847404 has been completed. It was found that, mechanically, there was nothing wrong with the gun. However, it was found that the trigger had been adjusted outside the plant, and the trigger pull was substantially below factory specifications.

We will, Mr. MacFarland, as Mr. Potter promised, install a new trigger mechanism adjusted and set to factory specifications. Also, this will have a safety without the bolt lock, as you requested in your letter.

We are sorry for the inconvenience, but thank you for the opportunity to be of service.

Sincerely,

A handwritten signature in dark ink, appearing to read "R.L. St. John". The signature is written in a cursive, flowing style.

R.L. St. John
Product Service

RLSJ:nb