

January 27, 1984


-2-

This type of problem is generally associated with high-pressure reloads.

Remington Arms Company, Inc. does warranty its products against any defects in materials and workmanship. However, under the circumstances when the damage resulted from a condition beyond our control, we cannot of course, assume any responsibility or liability for the present condition of the rifle, or for your missed trophy. However, we do want to be as helpful as possible to you and, as a gesture of customer good-will, are replacing the trigger assembly in your rifle at no-charge.

Thank you for having afforded us this opportunity to be of service to you, and we trust that our handling meets with your approval.

Sincerely,



J.A. Stekl, Supervisor  
Product Service

JAS:tpg