

Reaper

Trip pull $4\frac{1}{2}$ #

Sea lift 10105"

Paras well surrounded that

Heavy icing on bottom of receiver and in/on
trip assembly

Cannot duplicate complaint at this time
Gen functions as designed.