

Jim & Shirlene McComb
4802 Precipice Cove
Austin, Texas 78731

RECEIVED

JAN 08 1985

J. D. GLENN

December 30, 1985

Firearms Product Manager
Remington Arms Company, Inc.
939 Barnum Ave.
P.O. Box 1939
Bridgeport, Cn. 06601


RE: Model 700 BDL
SN # B6561158

Gentlemen,

On a recent hunting trip the above mentioned rifle discharged when I touched the safety lever. I was examining the stock for what looked like a chip in the slot for the safety, when I pushed the lever it jumped forward and the rifle fired. Luckily the rifle was pointed in a safe direction and no one was hit.

I have talked to several other Model 700 owners and find this problem has occurred with others and I would like to know how I can get the rifle repaired or replaced.

Sincerely,


Jim McComb