

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 12, 1988

Mr. J.W. McCoy  
RR#2, Box 241  
Burlingame, KS 66413

Dear Mr. McCoy:

Your letter of November 13, 1987, that was addressed to our Bridgeport, Connecticut facility, regarding the accidental discharge of your Remington Model 700 ADL rifle, serial number 99734, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you described, and that your son-in-law was injured as a result of the occurrence.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in the "fire" position.

Please, at your convenience, return the rifle via UPS, transportation C.O.D. to:

Remington Arms Co., Inc.  
Attn: J.A. Stekl, Supervisor  
Product Service  
14 Hoefler Ave.  
Ilion, NY 13357