

Dear Remington Arms Co,
 the enclosed gun (serial no. 134230)
 has a faulty or worn trigger
 mechanism. It has been occasionally
 firing prematurely as the safety is
 pushed forward or the bolt is
 lowered to the cocked position.

The last accident occurred in my
 garage as I worked some handloads
 through the chamber. one live round
 went off and I was able to duplicate
 the premature firing on empty shell cases.

Had I not been practicing good gun
 safety during these premature firings
 a serious accident might have resulted.

I am the original owner of this gun
 which was purchased in 1965 or 66. It
 (over)