

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

July 27, 1988

Mr. Nicholas Moccia
49 Ridgecrest Ave.
Staten Island, NY 10312

Dear Mr. Moccia:

Examination has been completed on the Model 700 BDL 30-06 caliber rifle, serial number A6417602, which you returned to us because "it fired when I took the safety off".

The returned firearm, which was produced in 1977, was found to contain our high pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests prior to shipment from our factory.

The general condition of the gun appeared to be good, however it was noted that the stock had numerous mars and scratches. In going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal.

Testing and subsequent disassembly of the trigger assembly revealed that the over-travel adjustment had been improperly set at our factory and the trigger return spring was binding. However, numerous cyclings of the firearm were conducted attempting to duplicate the condition that you described and the rifle functioned as designed with no accidental discharges.

Therefore, we will replace the present trigger assembly with a new one at no charge to you in the hope that your confidence in the rifle will be restored. Please allow approximately two (2) weeks for processing and return of the gun.