

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 23, 1990

Nixa Country Gun & Pawn
Route 5, Box 35
Nixa, MO 65714

Dear Sir:

Examination has been completed on the Model 700 ADL 30-06 caliber rifle, serial number B6415405, that you returned to us a short time ago because, "when the safety is taken off the gun goes off."

The returned firearm, which was produced in October of 1982, has been thoroughly examined and found to have our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the rifle appeared to be good and, in going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal. Trigger pull was measured at 4-1/2 pounds and the sear-lift with the safety in the "on-safe" position was also well within specifications at .0125".

Examination of the rifle and trigger assembly could not duplicate the reported malfunction. Many attempts were made to cause the rifle to fire upon movement of the safety from the "safe" to "fire" position, but it would not malfunction. The only way the rifle could be made to fire was with the safety in the "fire" position and the trigger pulled, functioning as designed.

Since we found the firearm to function properly in every respect, we are prepared to return it in its present condition. However, if you desire, we will install a new trigger assembly at no-charge, as