

1-800-275-6380

NO CARBON PAPER REQUIRED: Type or write on original - Impression will automatically appear on copies beneath

NORCKAUER ASSOCIATES

10220 Florida Blvd.
BATON ROUGE, LA 70815

(504) 272-3620

Message
Reply

DATE:

1/25/89

FILE NO.

F99476

ATTENTION:

Service Dept.

SUBJECT:

Remington Model 700BDL
code LX ser# 6617486
30-06 caliber

PRIORITY

- ☐ URGENT!
☐ SOON AS POSSIBLE
☐ NO REPLY NEEDED

Remington Arms Co., Inc.
Service Dept.
I lion New York

13357

Subject firearm is being returned for repairs to safety.
Customer claims firearm discharged when moving safety
button from safe to fire position, this happened when
the customer was attempting to unload his firearm after
a day of hunting. The customer would also like
the safety to be converted to the new style safety
that does not lock the bolt down when in the
safe position. Please send Estimate on repairs.

SIGNED:

Thank You
Dan Calvert

DATE OF REPLY:

REPLY TO:

Dan Calvert

SIGNED:

SENDER: MAIL RECIPIENT WHITE AND PINK SHEETS.

RECIPIENT: WRITE REPLY. RETURN WHITE TO SENDER. KEEP THIS PINK COPY.