

RECEIVING AND ESTIMATING REPORT

CUST NO: 019191 C.O.D		COMMENTS	
TIAL	CUSTOMER ORDER NO.		
CS			
TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
0/30/91	11/04/91	EV 10-79	A6834725
MODEL AND GRADE		ORDER	
700 7MMAG BDL		R 91-22215	
ACCESSORIES SCOPE BASE L/SIGHTS			

FROM:

NORTH CRAFTS FIREARMS
STAR ROUTE BOX 70
HOYES RD
FRIENDSVILLE MD 21531
USA

SHIP TO:

NORTH CRAFTS FIREARMS
STAR ROUTE BOX 70
HOYES RD
FRIENDSVILLE MD 21531
USA

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/> CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
				11-11-91	UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Safety malfunction, causes gun to fire without pulling the trigger.

MAIN FAULT

do record, internal trigger parts are not moving freely - trigger assembly is contaminated with a gummy, sticky residue. Trigger movement is being impeded by above substance in trigger assembly and plates. Trigger pull measured at 62 pounds; var. lift is .0095"

RTS

Clean trigger assembly if possible - if not, offer new trigger assembly at no added cost, as a gesture of goodwill

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90