

REPAIR GUN UPDATE FUNCTION: N (N)EXT (P)REV (U)PDATE (I)NO (E)XACT 03/31/94
 ENTER REPAIR NUMBER -----> 9203077 13 45 54
 SERIAL NO: A6346902 NEW SERIAL NO: MODEL: 700
 FROM: (CUST NUM: 056921) PAYNECLAYT GA/CAL: 30-06
 PAYNE, CLAYTON L TYPE: ADL
 1360 GIBSON DRIVE ACCESSORIES: W/STUDS

BIRMINGHAM AL 35214
 SHIPPED TO:

DATE CODES: WI
 OTHER ACCESSORIES:

COMMENTS: W/LEUPOLD 2X7 SCOPE & SEE THRU SCOPE MNTS

DATES:		TO	FROM	
RECEIVED	01 17 92	GALLERY	03 12 92	03 16 92 ENTERED BY: FPS
OPENED	01 24 92	PROD SERV	02 18 92	02 20 92 REPAIRMAN: EZ
ESTIMATED	02 26 92	TAG GUNS	00 00	TYPIST:
PROMISED	00 00 00	REJECTED	00 00	CORRESPONDENT:
GO AHEAD	00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: D
SHIPPED	03 25 92			

BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9203077 CHARGE (AWAIT RESP) CREDCRD INV PRI 03/31/94
 CUSTOMER NAME: PAYNE, CLAYTON L 13 46 22

REQUEST: 3 TIMES, FIRED WHEN SAFETY RELEASED
 MAIN FAULT: CANNOT DUPLICATE COMPLAINT AFTER MANY ATTEMPTS - REMOVAL OF
 BARRELED ACTION FROM STOCK REVEALED DIRT & EXCESSIVE OIL ON
 UNDERSIDE OF METAL - TRIGGER ASSEMBLY IS EXCESSIVELY OILY &
 DIRTY ALSO -

DATE OF MFG: 08-88
 PARTS: \$ 0.00 1 26345 TRIGGER ASSEM RH
 LABOR: \$ 0.00 REPLACE TRIGGER ASSEM AT 1/2 NORMAL COST, AS A GESTURE
 \$ 0.00 OF GOOD WILL -
 \$ 25.00 REPAIR CHARGE -
 \$ 0.00 TEST
 \$ 0.00 EZ/HAR
 \$ 0.00 * RETURN SCOPE & MT. IN CABINET

1360 GIBSON &
 B'HAM, AL 35214