

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 24, 1989

Mr. James R. Perrigo  
%Malone Plumbing & Heating  
Elm Street Rd.  
Malone, NY 12953

Dear Mr. Perrigo:

Examination has been completed on the Model Mohawk 600 243 caliber rifle, serial number 6392261, that you returned with the alleged complaint that the rifle fired when the safety moved to the fire position.

Your Model 600, which was produced in January of 1971, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests prior to being shipped from our factory.

The general condition of the rifle was good for a firearm of this age. The headspace, recoil shoulders and chamber were found to be normal.

Many attempts were made to cause the rifle to fire upon releasing the safety, without success. The factory seals were intact on the trigger adjusting screws indicating that no adjustment had been made to the trigger assembly outside the factory. The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed. Trigger pull was measured as was sear lift with the safety in the on safe position, and was well within specifications.

DECL. FINAL  
R 89-03896  
make repairs no charge