

RECEIVED

MAR 09 1989

J.A. Smith

*Pls. set up  
file.*

March 1, 1989

Remington Arms Company  
14 Hoetler Avenue  
Ilion, New York 13357

c/o Arms Division

Re: Remington Model 700  
30-06 Rifle  
Serial #A6409076

Gentlemen:

*Sent via UPS.*

I am sending the ~~enclosed~~ 30-06 Rifle to you for repair.  
Local gunsmiths in Salt Lake City are unable to make the  
necessary repair.

When the safety is moved from "on position" to "fire  
position" the rifle fires or discharges, without pulling  
the trigger. This happens only occasionally and generally  
after the safety has been in the "on position" for a while.


The rifle has "accidentally fired" twice during hunting  
trips, almost killing someone each time.

Please advise me at the address below of repair charges  
and I will remit as soon as possible.

Sincerely,

*Duane M. Peterson*

Duane M. Peterson  
7107 South 400 West, #1  
Midvale, Utah 84047  
(801) 255-3503



DMP/jh