

P.I. Yes GUN EXAMINATION REPORT NUMBER: _____ MODEL: M 700 ADL
 GENERAL CONDITION: Good R #: PA.
 OUTSIDE WORK: Turpin Engagement & Seal C DATE: 12/8/71
Barber FROM: Thomas Brown
 FIRED AMMO TYPE: _____
 & CONDITION: _____ GUN #: 6372713
 PROOF: ✓ INSP.: ✓ TEST: ✓ CODE: DT 9/70
 HEADING: Not checked GA./CAL.: 20/06
 BREECH OPENING: _____ CHECKED BY: Henry R. R.
 RECOIL SHOULDERS: _____ APPROVED: [Signature]
 CHAMBER: _____ APPROVED: Wm 12/10/71
 TEST: Flac - Examined in attorney's office APPROVED: St. Louis 12/10/71 ^{LM}
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

Turpin Engagement Screw seal and stake
broken



COMPLAINT: Fires when safe is released.

INCIDENT: Fired on releasing safe. Shot spectator.
fact

COMMENTS: Screw, Connector engagement OK. Shift-Turpin. No
protrusion on left side of bolt. Sufficient engagement
of F.P. Head to screw. Shift acceptable. No protrusion
of Screw & Connector. Turpin screw in housing. Turpin
Engagement Screw seal and stake broken. screw driven
works on screw. Other adjustment screws sealed. Turpin
Engagement Screw rotated when Turpin Pin trapped with
hammer. Incident could not be duplicated.