

MAR 05 1987

K. D. GREEN

JAS

Larry Reed
P.O. Box 549
Alva, Oklahoma 73717
Feb. 22, 1987

RECEIVED

MAR - 2 1987

ARMS SERVICE

Remington Arms Co., Inc.
Parts Dept., Arms Service Div.
Ilion, New York 13357

Dear Sirs:

I have two Remington rifles that I have had trouble with and thought you might be able to help solve the problems.

The first rifle is a Mod. 700, Ser. #6857265, Cal. 25-06. I had a premature discharge when I pushed the safety forward. I am sure I did not pull the trigger, as I had my hand on the outside of the trigger guard.

The second rifle is a Mod. 722, Ser. #208795, Cal. 222. On two different occasions I have ejected an unfired cartridge, leaving the projectile in the barrel. The ammo being used was 222 Remington (55 Gr metal case - R222R4-C 29K D6637). The barrel is clean and free of foreign objects.

Any help you can give me in correcting these problems will be greatly appreciated.

Thank You,

Larry Reed
Larry Reed