## **BARBER - Kinzer PPS GAL RE0004281**

Mr. Rothell, as a gesture of good-will, we will install a new trigger assembly at no-charge, to restore your confidence in the rifle. Please allow 2 to 3 weeks to have the work performed.

Thank you for affording us this opportunity to be of service, and we trust that our handling meets with your approval.

Sincerely,

a Stike

J.A. Stekl, Specialist Product Service

JAS:tpp

Remington Arms Company, Inc.