

July 31, 1989

Remington Arms Company, Inc.
Arms Service Division
Ilion, New York 13357

Dear Sir:

Enclosed is my complete model 700 ADL
rifle in .243 caliber (Serial # 6260588).

The rifle is having some type of
trouble in the trigger, bolt, or safety area?
Sometimes the rifle discharges as you are
emptying the magazine through the opening
and closing of the bolt, sometimes the
rifle hesitates to fire as the trigger is
pulled - there is a distinct click and
a moment later the rifle discharges. It
does not do this everytime, however the
rifle has become unsafe to handle while
loaded.

The rifle is very accurate, and a pleasure
to hunt with, and I hope you can find the
problem and correct it.

(over)