

215-774-5463

REPAIR GUN UPDATE FUNCTION: N (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 07/31/93  
 ENTER REPAIR NUMBER -----> 9314408 07 35 36  
 SERIAL NO: 328013 NEW SERIAL NO: MODEL: 700  
 FROM: (CUST NUM: 080530 ) SCHARNITZS GA/CAL: 308 WIN  
 SCHARNITZ, SCOTT M. TYPE:  
 605 BUCKINGHAM DR. ACCESSORIES: L/SIGHTS  
 NORTHAMPTON PA 18067 SCOPE BASE  
 SHIPPED TO: L/WOOD  
 L/FOLLOWER  
 L/MAG SPRING  
 DATE CODES: AR 3-68  
 OTHER ACCESSORIES:

COMMENTS: ATTN: DENNIS SANITA

DATES:		TO		FROM		
RECEIVED	06 25 93	GALLERY	06 30 93	07 06 93		ENTERED BY: FPS
OPENED	06 29 93	PROD SERV	00 00 00	00 00 00		REPAIRMAN: REF
ESTIMATED	07 06 93	TAG GUNS	00 00			TYPIST:
PROMISED	00 00 00	REJECTED	00 00			CORRESPONDENT:
GO AHEAD	07 06 93	CASH RECEIVED:\$	0.00	BILL TYPE: D		
SHIPPED	07 09 93					
BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT						

REPAIR NUMBER: 9314408 CHARGE (WORK DONE) CREDCRD INV PRI 07/31/93  
 CUSTOMER NAME: SCHARNITZ, SCOTT M. 07 35 48

REQUEST: RIFLE DISCHARGED WHEN SAFETY WAS MOVED.  
 MAIN FAULT: UPON RECEIPT RIFLE INOPERATIVE. TRIGGER WILL NOT RETRACT  
 EXAMINATION REVEALED THAT THE SEALANT HAD BEEN REMOVED  
 FROM THE TRIGGER ADJUSTMENT AND STOP SCREWS. BOTH SCREWS  
 BACKED OUT OF HOUSING. TRIG. PULL BELOW 2 LBS FACTORY SPEC.  
 RIFLE ADJUSTED OUTSIDE FACTORY. MFG. 1968  
 PARTS: \$ 0.00 1 26345 TRIGGER ASSEM RH  
 LABOR: \$ 20.00 REPLACE TRIGGER ASSEM COMPLETE AT SPECIAL PRICE  
 \$ 0.00 CLEAN ACTION, REQUEST TRIG PULL 3 LBS TO 3 1/2 LBS.  
 \$ 0.00 TEST WITH SLAVE STOCK, ETC.  
 \$ 0.00 REF;CM

REPAIRMAN'S INITS: REF NUM OF WKS: 03 CORRESPONDENT'S INITS:  
 TOTAL VALUE:\$ 20.00 PF1 = INQ PF2 = ESTIMATE  
 NO MORE DATA AVAILABLE FOR THIS REPAIR

*Frank*  
*Change N/S Safety no bolt lock*  
*8/2/93*