

BARBER - Kinzer PPS GAL RE0004397

REPAIR GUN INQUIRY FUNCTION: E (N)EXT (P)REV (I)NQ (E)XACT 05/10/93  
 9225724 11 36 42  
 ENTER SERIAL NUMBER -----> A6564027 MODEL: 700  
 FROM: SCHMIDT GA/CAL: 270  
 SCHMIDT, PATRICK A TYPE: BDL  
 3241 JACKS RUN RD ACCESSORIES: SLING STRAP  
 W/STUDS  
 W/SWIVELS  
 WHITE OAK PA 15131  
 SHIPPED TO:

DATE CODES: LQ 2-78  
 OTHER ACCESSORIES:

COMMENTS:

DATES:		TO	FROM	
RECEIVED	11 23 92	GALLERY	12 30 92	12 31 92 ENTERED BY: JJM
OPENED	12 01 92	PROD SERV	00 00 00	00 00 00 REPAIRMAN: BW
ESTIMATED	00 00 00	TAG GUNS	00 00	00 00 00 TYPIST:
PROMISED	00 00 00	REJECTED	00 00	00 00 00 CORRESPONDENT:
REPAIRED	00 00 00			
SHIPPED	01 12 93			
BILL TYPE COD				

PF1 = VIEW DETAIL  
 PF4 = SERIAL NUMBER BROWSE

REPAIR NUMBER: 9225724 CHARGE (AWAIT RESP) COD PRINTED 05/10/93  
 CUSTOMER NAME: SCHMIDT, PATRICK A 11 37 16

=====

REQUEST: "HESITATION WHEN FIRST SHOT FIRED"

MAIN FAULT: COULD NOT DUPLICATE CONDITION CUSTOMER DESCRIBED. HOWEVER  
 DISASSEMBLY OF RIFLE REVEALED THAT A GUMMY SUBSTANCE WAS  
 FOUND ON THE TRIGGER ASSEMBLY, AND BOLT STOP. CLEANING RE-  
 QUIRED. TRIGGER PUL 5 1/2 LBS.- SEAR-LIFT .007  
 DATE OF MFG: 02-78

PARTS: \$ 30.00 1 26345 TRIGGER ASSEM RH  
 LABOR: \$ 0.00 BASED ON STICKY/GUMMY CONDITION OF TRIG ASSEM., REPLACE  
 \$ 0.00 TRIG ASSEM. AT 1/2 NORMAL COST, AS GESTURE OF GOOD-WILL  
 \$ 0.00 CUSTOMER HAS AUTHORIZED REPAIR UNDER \$50.00 -  
 \$ 0.00 APPROVED 12/29/92 PER PHONE  
 \$ 0.00 CLEAN - TEST  
 \$ 0.00 BW/HAR

REPAIRMAN'S INITS: BW NUM OF WKS: 00 CORRESPONDENT'S INITS:  
 TOTAL VALUE:\$ 39.80 PF1 = INQ PF2 = ESTIMATE  
 NO MORE DATA AVAILABLE FOR THIS REPAIR