

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 24, 1989

Mr. Clyde E. Seybert  
1113 Jefferson St.  
McKeesport, PA 15132

Dear Mr. Seybert:

Examination has been completed on the Model 700, 300 Win. Magnum, barreled action, serial number B6367742 that you recently returned to us.

The barreled action, which was produced in December of 1981 has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests prior to being shipped from our plant.

The general condition of the action appeared to be very good, except for an excessive amount of lubricant. In going over the individual parts, we found headspace, recoil shoulders, and chamber all to be normal.

Examination of the action and trigger assembly could not duplicate the malfunction you reported. Many attempts were made in numerous ways to duplicate the problem. The one factor noted was that the factory seal had been broken on the trigger pull adjusting screw, indicating an outside the factory adjustment had been made. The trigger was measured at 2-1/2 pounds, which is below our factory specifications. The sear lift with the safety in the "on-safe" position was well within specifications at .012". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.