

-2-

Since we found the mechanisms to function normally in every respect, except for the light trigger pull, we are prepared to return it to you after readjusting the trigger to factory specifications and resealing the adjustment screws. We strongly advise that no adjustments to the trigger be made by anyone not factory authorized and trained. Also, lubrication should be kept to an absolute minimum. However, as a gesture of good will and to restore your confidence in the rifle, we will install, at no charge, a new trigger assembly, if you so desire. We will await your decision and reply.

Thank you for affording us the opportunity to examine the action and report our findings.

Sincerely,



R.L. St. John
Product Service

RLSTJ:tp

Remington Arms Company, Inc.