

used sparingly and not let accumulate in or on the trigger assembly, as both of these conditions could adversely affect the operation of the trigger assembly.

As a gesture of good-will, we are installing a new trigger assembly, and cleaning the action at no-charge. Please allow 2 to 3 weeks to have this work performed.

Thank you for having afforded us this opportunity to be of service, and we trust that our handling will meet with your approval.

Sincerely,


D.J. Sanita
Product Service

DJS:tpp

Remington Arms Company, Inc.