

ET08360

BARBER - 5.22.06r0002530

PROJECT # 241095 AMMO REMINGTON 30.06 180 GRAIN R30064

19-6-ş


HOT FUNCTION TEST GUN # C 21 ----SERIAL # 71001761

- # 1 PLACE GUN C 21 AND 100 ROUNDS AMMO IN PRE-HEATED CHAMBER FOR 13 HOURS AT 120 DEGREE F.
- # 2 TOOK GUN C 21 AND 20 ROUNDS OF AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS. LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE.
 - CYCLED SAFETY EVERY FIVE ROUNDS. PUT GUN C 21 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.
- # 3 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.
 LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE.
 CYCLED SAFETY EVERY FIVE ROUNDS.
 PUT GUN C 21 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.
- # 4 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.
 LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE.
 CYCLED SAFETY EVERY FIVE ROUNDS.
 PUT GUN C 21 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.
- # 5 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.
 LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE.
 CYCLED SAFETY EVERY FIVE ROUNDS.
- # 6 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PREMEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS. LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE CYCLED SAFETY EVERY FIVE ROUNDS.

ra≴ ∠sints

7 CLEANED AND INSPECTED FIRING PIN HEAD (LOOSE) FIRING PIN TIP (LOOSE).

ET08361



ET08362