

INITIAL FPS	CUSTOMER ORDER NO.		CALL TAG ATTN: TOM NAGLE			
DATE RECEIVED 05/05/94	DATE OPENED 05/05/94	DATE CODE XU 12-71	SERIAL NUMBER 6508205	NEW SERIAL NUMBER	MODEL AND GRADE 700 22-250	BDL/VAR
ACCESSORIES W/STUDS						

L/REAR SIGHT

FROM:

SHIP TO:

Handwritten signature: Fred Saper

SMITH, GEORGE J.
8560 W. 10 RD.
MESICK

MI 49668

SMITH, GEORGE J.
8560 W. 10 RD.
MESICK

MI 49668

CUST NO: 096968 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED					REPAIR CHARGE <i>20.00</i> EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP					F1	F1
BOLT ASSY.					F2	
BARREL ASSY.			D1	E3	F3	
REC. ASSY.			D2	E4	F4	
WOOD			C1	E5	F5	
METAL			C2			

MAIN FAULT

Upon receipt, we were unable to duplicate the customer concern. Examination reveals that the cam engagement has been set and is correct on the factory. The problem is missing from the original record and the trigger support is bad. There is no adjustment present on trigger.

PARTS

COMMENTS

Revised cam part trigger assembly at 1/2 normal adjustment set as per spec. and good and.
Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94