OBDER

Return To Factory

FIREARMS NOT REPAIRED AT SPORTS WORLD

Customer: WALMART 813 Date To Factory: 06/30/92

Address:

State, City, Zip:

Attn: CLAIMS CLERK

Return Claim No.01-0813-727

Sports World Repair Number : K12769

Package ID Number :769

Reason For Returning To Manufacture : STOCK CRACKED BY BOLT. ALSO WHEN BOLT CLOSES IT SOMETIMES RELEASES FIRING PIN CAUSING ACCIDENTAL DISCHARGE OF RD.

Please Note: We are unable to repair the above mentioned repair at Sports World, Inc. due to the type of repairs needed, therefore, we have sent your firearm to the following manufacturer for repairs:

Remington Arms Company, Inc. Arms Service Division Ilion, NY 13357

CLAIMS CLERKS, please put this note with your paper work for RC#01-0813-727

MANUFACTURE NOTE: After repairs are made, please return directly to:

Sports World, Inc. 5800 S. Lewis #154 Tulsa, OK 74105 1-918-742-4027

Thank you,

Sports World, Inc.