

RECEIVING AND ESTIMATING REPORT COMMENTS

INITIALS: **PS** CUSTOMER ORDER NO. **R 94-12134**

DATE RECEIVED: **04/06/94** DATE OPENED: **04/06/94** DATE CODE: **AA 3-B0** SERIAL NUMBER: **A6879484** NEW SERIAL NUMBER: MODEL AND GRADE: **700 30-06** ADL

ACCESSORIES

FROM: **STEVENS WHOLESALE INC**
7023 US 60
ASHLAND KY 41101

SHIP TO: **STEVENS WHOLESALE INC**
7023 US 60
ASHLAND KY 41101

CUST NO: 021584 C.O.D.

ACCOUNT NUMBER ACCOUNT NUMBER INC WRITE ☐ FROM DATE ESTIMATED VIA **UPS**

GUN CONDITION
☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE: **20.00**
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: *We could not duplicate the Customer Concern. Removal of the trigger assembly would be required and trigger assembly can be used with any resistance. The trigger adjustment screws have been set to the point that the trigger (adjustable) trigger and follow over main press.*

PARTS: *Trigger Pin - 1/4" dia
Spring - D10
22345 trigger assembly*

COMMENTS: *Recheck trigger assembly and clean action at 1/2 hour. Recheck trigger and follow over main press.*

REPAIRMAN: *CC* PROOF: CLEAN: TEST: TARGET: PATTERN:

GALLERY TESTER: DATE: DATE: DATE: DATE: DATE:

to A/S 5/19/94