TTT - 64

Dromber 20, 1002

-2-

We trust that we have clarified the circumstances that could possibly have caused the accidental firings and, as a gesture of good-will, we can replace the present trigger assembly with a new one that will allow opening the bolt while the safety is in the "on safe" position at ne-charge, to insure that your faith in the rifle is restored, Tr. we can clean the original assembly before returning the rifle. We will await your decision and reply.

Thank you for having afforded us this opportunity to examine your rifle and to be of service.

Sincerely,

J.A. Stoki, Supervisor Pireems Product Service

JAS: tpp				,
25	•	En STOFFE ( De	- COM	<b>z</b> 65925.
26.5	) z (	2 8.6260707	2270	
5 5	05 5 5 5 5	15 Release to when their 15 Ch	241 T	·
	7118 954 954			
j L	2 5 5 8 2 4 5 8 2 4 5 6			
E.	SCO Wish		*****	
44	A75.		MATERIAL S	
. m-	8	MEDINO OV	TAIL	
E .		Thenk You! US & San	7074	i